

RIO with a report to AECEDR

Const Div with ref to department



Building Safety Certificate of

Maahabadi Subd upon visual

inspection building to be in

safe condition and no cracks were  
observed.

Hence further submit for  
necessary attn at your end



# Annexure- D

## BUILDING SAFETY CERTIFICATE

No. CDL/RK/10/28

Dated: 26/05/26

It is certified that the existing building Mahabodhi Reerdhhi school (name of the building or premises) at Saboo.

.....(address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	✓					

The building is owned/occupied by Mahabodhi Reerdhhi School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Mohd. Quam (Name of Department/ Govt.) on 26/5/26 (date of inspection) in the presence of Asst. Ex. Engineer Tel (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 26/5/26 for a period of 2 year years in accordance with rule and subject to compliance of the specific conditions as appended.

1. /
- 2.
- 3.
- 4.

Issued on 26/5/26 at Tel by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: [Signature]

Name: [Signature]

Designation: EA. Engineer

Name & Address of Department/ Office: Tel

Executive Engineer,  
Public Construction Division